

Lesson 17: Synchronous Machines

ET 332b

Ac Motors, Generators and Power Systems

Lesson 17_et332b.pptx



Learning Objectives

After this presentation you will be able to:

- Explain how synchronous machines operate.
- Draw the per phase circuit model of a synchronous machine.
- Write and utilize the power equations for synchronous machines.
- Use machine equations to determine a machines operation point and power
- Compute motor torques

Lesson 17_et332b.pptx



Synchronous Machines


Synchronous Motors – Convert electrical power into mechanical power. They operate at a constant speed

Synchronous generator (Alternator) - Convert mechanical power into electrical power (3-phase). Constant speed of mechanical drive gives constant frequency ac

Lesson 17_et332b.pptx



Basic Construction of Synchronous Machines



Lesson 17_et332b.pptx



Operational Theory for Synchronous Machines

Motor Operation

- 1.) Armature is connected to 3-phase source - rotating magnetic field formed in armature windings
- 2.) Rotor (field) is energized by dc source. Creates a magnetic dipole
- 3.) Motor has no starting torque, must be started as induction motor. Damper windings engaged (induction motor action). Motor accelerates to almost synchronous speed.
- 4.) Damper winding disengaged, motor stays locked to rotating magnetic field and produces torque

Synchronous motors operate at constant speed regardless of load applied

Lesson 17_et332b.pptx



Operational Theory for Synchronous Machines

Alternator Operation

- 1.) Prime mover attached to machine shaft.
- 2.) Dc supply applied to rotor to make magnetic dipole
- 3.) Prime mover accelerates machine to operating speed. Speed and number of poles determine frequency
- 4.) Armature (stationary winding) generate 3-phase voltages

Note: mechanical power input determines electrical power output exciter voltage level determines alternator terminal voltage

Lesson 17_et332b.pptx



Synchronous Motor Operation

Motor speed constant at synchronous speed, n_s

$$n_s = \frac{120 \cdot f}{P}$$

Where f = power system frequency (Hz)
 P = number of motor poles

Speed can only be changed by changing system f or number of poles in machine

Lesson 17_et332b.pptx



Motor Reaction to Application Load Application

1.) Motor rotor is in phase with rotating armature (stator) field

2.) Mechanical load is applied, rotor slows instantaneously then returns to n_s .

3.) Instantaneous speed reduction causes rotor to lag rotating field by an angle (phase shift) Angular shift called power angle (δ).


5.) Torque and power developed is related to angular shift

High values of δ will cause rotor to slip out of synchronization with rotating magnetic field. Condition called out-of-step operation or pole slipping (Causes current pulses in armature windings)

Lesson 17_et332b.pptx



Synchronous Motor Operation



Lesson 17_et332b.pptx



Counter-EMF Components in Synchronous Machines


Field flux induces voltage into armature (stator) due to rotation (E_f). E_f depends on I_f (dc field current) and n_s . The parameter E_f , called excitation voltage.

Rotating magnetic field in armature (stator) induces voltage in armature called armature reaction voltage. (E_{ar}) This voltage depends on the speed of the rotating magnetic field produced by the applied voltage

Lesson 17_et332b.pptx



Per Phase Circuit Model




Motor Operation $\bar{V}_T = \bar{I}_a [R_a + j(X_l + X_{ar})] + \bar{E}_f$

- Where:
- V_T = applied V /phase (phasor)
 - I_a = armature current (phasor)
 - X_l = armature leakage reactance ohms/phase
 - X_{ar} = armature-reaction reactance ohms/phase
 - R_a = armature resistance ohms/phase

Lesson 17_et332b.pptx



Simplified Synchronous Machine Model



Let $X_s = X_l + X_{ar}$ = synchronous reactance
 $R_a \ll X_s$ so it is usually ignored

For alternator operation,
 reverse the direction of I_a


$\bar{V}_T = \bar{E}_f + \bar{I}_a \cdot jX_s$

- Where
- V_T = per phase terminal voltage (phasor)
 - E_f = voltage behind synchronous reactance
 - I_a = armature current (phasor)
 - X_s = synchronous reactance

Lesson 17_et332b.pptx



Power Transfer in Synchronous Machines



$$\begin{array}{ccc}
 \delta & & I_a \cdot X \\
 E_f & \left. \vphantom{E_f} \right\} E_f \sin(\delta) & \theta_i \\
 & & I_a \cdot X_s \cos(\theta_i)
 \end{array}$$

From phasor diagram above $E_f \sin(\delta) = I_a \cdot X_s \cos(\theta_i)$

Lesson 17_et332b.pptx



Power Transfer In Synchronous Machines

Multiplying the equation from the phasor diagram by V_T and dividing both sides by X_s gives power/phase.

$$\frac{|\bar{V}_T| \cdot |\bar{E}_f|}{|X_s|} \sin(\delta) = V_T \cdot I_a \cos(\theta_i)$$

Where: θ_i = machine power factor.

Total 3-phase power is

$$P_{in} = \frac{-3|\bar{V}_T| \cdot |\bar{E}_f|}{|X_s|} \sin(\delta) \quad \text{In terms of machine quantities}$$


$$P_{in} = -3V_T \cdot I_a \cos(\theta_i) \quad \text{In terms of input quantities}$$

Lesson 17_et332b.pptx



Maximum Power Transfer in Synchronous Machines

There is a maximum power that a synchronous machine can develop before it loses synchronism



Lesson 17_et332b.pptx



- Example 17-1:** A 100 hp 460 volt 60 Hz 4-pole synchronous motor is operating at rated conditions and a power factor of 80% leading. The motor efficiency is 96% and the synchronous reactance is 2.72 ohms/phase. Find:
- developed torque;
 - armature current;
 - excitation voltage (E_f);
 - power angle;
 - the maximum torque the motor can develop without loss of synchronization. (pull-out torque).

Lesson 17_et332b.pptx



Example 17-1 Solution (1)

Find the input power

$$a.) P_{\text{shaft}} = 100 \text{ hp} = (746 \text{ W/hp})(100 \text{ hp}) = 74,600 \text{ W}$$

No losses in Armature so

$$\eta = \frac{P_{\text{shaft}}}{P_{\text{mech}}} \Rightarrow P_{\text{mech}} = P_{\text{in}}$$

$$P_{\text{in}} = \frac{P_{\text{shaft}}}{\eta}$$

$$\eta = 96\% \quad \eta = \frac{96\%}{100} = 0.96$$

$$P_{\text{in}} = \frac{74,600 \text{ W}}{0.96} = 77,708 \text{ W}$$

Motor operates at synchronous speed

$$n_s = \frac{120f}{p} = \frac{120(60 \text{ Hz})}{4} = 1800 \text{ RPM}$$

$$T_p = \frac{7.46 (P_{\text{in}})}{n_s} = \frac{7.46 (77,708 \text{ W})}{1800 \text{ RPM}} = \boxed{304.16 \text{ ft}}$$

Lesson 17_et332b.pptx



Example 17-1 Solution (2)

b.) ARMATURE CURRENT I_a

$$P_{\text{in}} = 3V_T I_a \cos \theta_i$$

Assume Y-connected motor

$$V_T = \frac{V_{LL}}{\sqrt{3}} = \frac{960 \text{ V}}{\sqrt{3}} = 265.6 \text{ V} \quad \text{Phase V}$$

No losses in armature so $P_{\text{in}} = P_{\text{mech}}$

$$|I_a| = \frac{P_{\text{in}}}{3V_T \cos \theta_i} = \frac{77,708 \text{ W}}{3(265.6 \text{ V})(0.8)} = |I_a|$$

$$|I_a| = 121.9 \text{ A}$$

Now find the phase angle from the F_p . $\cos \theta_i = F_p = 0.80$ leading

Combine magnitude and phase angle

$$\boxed{\vec{I}_a = 121.9 \angle 36.87^\circ}$$

$$\theta_i = \cos^{-1}(F_p)$$

$$\theta_i = \cos^{-1}(0.8) = 36.87^\circ$$


+ Leading

Lesson 17_et332b.pptx



Example 17-1 Solution (3)

Find voltage behind synchronous reactance



Assume that V_T is the reference phasor


$$\bar{E}_f = 265.6 \angle 0^\circ - 121.9 \angle 36.87^\circ (2.72 \angle 90^\circ)$$

$$\bar{E}_f = 265.6 \angle 0^\circ - 331.568 \angle 124.9^\circ$$

$$\bar{E}_f = 534.9 \angle -29.7^\circ$$

$$\bar{E}_f = \bar{V}_T - \bar{I}_a X_s j$$

d.) Torque angle is the same as the angle on E_f



Lesson 17_et332b.pptx



Example 17-1 Solution (4)

Now find the pullout torque

e.) Pullout or max Torque occurs at P_{max} P_{max} occurs at $\delta = -90^\circ$ (MOTOR ACTION)

$$P_{max} = \frac{-3|\bar{V}_T||\bar{E}_f| \sin \delta}{X_s} \quad \sin(-90) = -1 \quad P_{max} = \frac{-3(265.6)(534.9)(-1)}{2.72}$$

$$P_{max} = 156,694 \text{ W}$$

Compute the torque from P_{max} and synchronous speed

$$T_{max} = \frac{7.04 (P_{max})}{n_s} \quad T_{max} = \frac{7.04 (156,694 \text{ W})}{1800 \text{ RPM}} = \boxed{61316 \text{ ft}}$$

Lesson 17_et332b.pptx



ET 332b
Ac Motors, Generators and Power Systems

 **END LESSON 17**

Lesson 17_et332b.pptx

