

Lesson 20_et332b.pptx

ET 332b

Ac Motors, Generators and Power Systems

LESSON 20 ALTERNATOR OPERATION OF SYNCHRONOUS MACHINES



Lesson 20_et332b.pptx

LEARNING OBJECTIVES

After this presentation you will be able to:


- Interpret alternator phasor diagrams under different load conditions.
- Explain the infinite bus concept and compute power delivered to an infinite bus.
- Explain how alternators are synchronized.
- Define alternator stiffness.



Lesson 20_et332b.pptx

ALTERNATOR OPERATION

Synchronous machines can convert from motor to generator operation by having the shaft driven by a source of mechanical power



Current exits for generator operation


Note: reversal of current direction in machine electrical model



Lesson 20_et332b.pptx

PHASOR DIAGRAMS OF MACHINE OPERATION

Motor operation: δ lags the terminal voltage V_T . Armature current I_a can either lead or lag V_T depending on value of excitation.



Leading I_a


Lagging I_a



Lesson 20_et332b.pptx

PHASOR DIAGRAMS OF MACHINE OPERATION

Machine with no mechanical load or power output. The torque/power angle, δ is 0 in this case




$\delta = 0$

Lesson 20_et332b.pptx

PHASOR DIAGRAMS OF MACHINE OPERATION

Generator operation (Alternator)




E_{f1} leads the terminal voltage for generator operation

Power factor angle can either lag or lead depending on field excitation

ALTERNATOR CIRCUIT MODEL

Synchronous Generator Equations and Model Circuit



Power equation (Watts/phase)

$$P_{in} = \frac{|\bar{V}_T| \cdot |\bar{E}_f|}{|\bar{X}_s|} \sin(\delta)$$

Note: equation is positive and δ is positive for Alternator (generator) operation


Voltage equation

$$\bar{V}_T = \bar{E}_f + \bar{I}_a \cdot j\bar{X}_s$$

- Where:
- V_T = terminal voltage/phase (V)
 - E_f = excitation voltage/phase (V)
 - I_a = armature current/phase (A)
 - X_s = synchronous reactance/phase (ohms)



GENERATOR LOADING




Speed Governor – device that regulates speed to match electric load
 Increased electrical load produces counter torque that prime mover must overcome or prime mover slows down



Lesson 20_et332b.pptx

INFINITE BUS CONCEPT

In large power systems, V_T and system frequency are assumed constant. Individual generators added to large system can not change V_T and f . Good approximation when generator small with respect to all other generation connected



Lesson 20_et332b.pptx

INFINITE BUS EXAMPLE

Example 20-1: 3-phase, 460 V, 2-pole, 60 Hz, wye-connected, synchronous alternator. $X_s = 1.26$ ohm/phase. Connected to an infinite bus and supplies 117 kW with a power angle of 25 degrees. Neglect losses and find:

- turbine torque supplied to alternator;
- excitation voltage;
- active, reactive power and machine power factor;
- neglecting saturation effects of the field, the excitation voltage if the field current is reduced to 85% of its original value in part a;
- the turbine speed for 60 Hz operation

Lesson 20_et332b.pptx

EXAMPLE 20-1 SOLUTION (1)

Find torque developed by prime mover to generate 117 kW neglecting losses

$$P_o = P_{in} \text{ neglecting losses}$$

$$T_D = \frac{7.04(P_{in})}{n_s}$$

Need synchronous speed

For 60 Hz operation

$$P = 2$$

$$f = 60$$

$$n_s = \frac{120f}{P}$$

$$n_s = \frac{120(60\text{Hz})}{2}$$

$$n_s = 3600 \text{ RPM}$$

Part e

$$P_{in} = 117,000 \text{ W}$$

$$T_D = \frac{7.04(117,000 \text{ W})}{3600 \text{ RPM}}$$

$$T_D = 228.8 \text{ lb-ft}$$

ANS Part a

Lesson 20_et332b.pptx

EXAMPLE 20-1 SOLUTION (2)

Find the excitation voltage E_f

$$P_o = P_{in} \text{ SO TOTAL } 3\phi P$$

$$P_{in} = \frac{3|\bar{V}_T| |\bar{E}_f| \sin(\delta)}{|X_s|}$$

Solve for E_f

$$|\bar{E}_f| = \frac{P_{in} |X_s|}{3|\bar{V}_T| \sin(\delta)}$$

$$|\bar{E}_f| = \frac{(117,000)(1.26 \Omega)}{3|\bar{V}_T| \sin(25^\circ)}$$

δ = angle of \bar{E}_f so

$$\bar{E}_f = 437.8 \angle 25^\circ \text{ V}$$

ANS Part b

Lesson 20_et332b.pptx

EXAMPLE 20-1 SOLUTION (3)

Part c.) Find S_{out} , P_{out} and Q_{out} of generator. Need armature current

$$\bar{S}_\phi = \bar{V}_{Tp} \bar{I}_a^*$$

$$\bar{V}_{Tp} = \bar{E}_f + \bar{I}_a jX_s$$

Solve for \bar{I}_a


$$\frac{\bar{V}_{Tp} - \bar{E}_f}{jX_s} = \bar{I}_a$$

$$jX_s = j1.26 \Omega/\text{phase} \quad \bar{V}_{Tp} = 265.6 \angle 0^\circ$$

$$\bar{I}_a = \frac{\bar{V}_{Tp} - \bar{E}_f}{jX_s} = \frac{265.6 \angle 0^\circ - 437.8 \angle 25^\circ}{j1.26 \Omega} = \frac{226.83 \angle -125.3^\circ}{1.26 \angle 90^\circ}$$

$$\bar{I}_a = 180 \angle -215.3^\circ = 180 \angle 144.7^\circ \text{ A}$$

$$360 - 215.3^\circ = 144.7^\circ$$



Lesson 20_et332b.pptx

EXAMPLE 20-1 SOLUTION (4)

Find the power phasor using the following formulas

$$\bar{S}_\phi = \bar{V}_{Tp} \bar{I}_a^* \text{ PER PHASE}$$

TOTAL POWER

$$\bar{S}_T = 3 \bar{V}_{Tp} \bar{I}_a^*$$

$$\bar{S}_T = 3(265.6 \angle 0^\circ)(180 \angle 144.7^\circ)^*$$

$$\bar{S}_T = 3(265.6 \angle 0^\circ)(180 \angle -144.7^\circ)$$

$$\bar{S}_T = 143,424 \angle -144.7^\circ \text{ VA}$$

CONVERT TO RECTANGULAR

$$\bar{S}_T = -117,000 \text{ W} - j82,971 \text{ VAR}$$

$P = -117,000 \text{ W}$ Generator Delivery to System
 $Q = -82,971 \text{ VAR}$ NEG VARS DELIVERED TO SYSTEM

EXAMPLE 20-1 SOLUTION (5)

Find the power factor and the change in excitation voltage

$$F_p = \frac{P_o}{|S_T|} = \frac{117,000 \text{ W}}{143,429 \text{ VA}}$$


$$F_p = 0.816 \text{ Leading}$$

Part d E_f for I_f reduced to 85% of rated
 Ignoring saturation $E_f \propto I_f$
 $E_{f2} = 0.85 E_{f1}$ $|E_{f1}| = 432.9 \text{ V}$ Part B
 $E_{f2} = 0.85(432.9 \text{ V}) = \boxed{372.13 \text{ V}}$ Ans
 Part d



PARALLELING SYNCHRONOUS GENERATORS

Required initial conditions: Machines must have same phase sequence (order of voltages) (ABC) or (BAC). Incorrect phase sequence causes short circuit.



Lesson 20_et332b.pptx

MEASURING SYSTEM/MACHINE FREQUENCY

Synchroscope - instrument to determine if machine frequency is the same as system frequency. Instrument indicates fast-slow operation by comparing the frequencies of the two voltages (system-generator)



Mathematically, phase shift is integral of frequency change

$$\phi = \int_0^t [f_s \pm f_g(t)] dt$$

Where: ϕ = phase shift
 f_s = system frequency
 $f_g(t)$ = generator frequency




Lesson 20_et332b.pptx

SYNCH EXAMPLE

Generator voltage lagging system voltage - crosses zero later in time

Also cause rotor oscillations which cause the generator to be unstable




Closing Generator breaker with phase shifts of greater than 10 degrees causes high armature currents and will trip the generator off line



Lesson 20_et332b.pptx

SYNCHRONIZING GENERATOR TO SYSTEM

Increasing speed of prime mover increases frequency which reduces phase difference




Lesson 20_et332b.pptx

SYNCHRONIZING GENERATOR TO SYSTEM

Phase shift near zero at t_s . Prime mover is accelerating the rotor ahead of the system voltage after this point. (V_g leads V_s)

Close generator breaker when phase is slightly leading system


Machine will remain locked to system frequency after breaker is closed assuming infinite bus



Lesson 20_et332b.pptx

STIFFNESS OF SYNCHRONOUS MACHINES

Stiffness -Ability of a synchronous machine to resist forces that pull it out of synchronism. Slope of the power-angle curve around a given operating point



Operating point in graph above is at δ_0

Lesson 20_et332b.pptx

STIFFNESS OF SYNCHRONOUS MACHINES

Remember power equation

$$P = \frac{3 \cdot |\bar{V}_T| \cdot |\bar{E}_f|}{|\bar{X}_s|} \sin(\delta)$$

To find slope, take derivative of P with respect to δ . This is defined as the stiffness

$$P_s = \frac{\Delta P}{\Delta \delta} = \frac{dP}{d\delta} = \frac{3 \cdot |\bar{V}_T| \cdot |\bar{E}_f|}{|\bar{X}_s|} \cos(\delta)$$

Units of P_s are watts/radian (or degree)

Lesson 20_et332b.pptx

STIFFNESS OF SYNCHRONOUS MACHINES

Example 20-2: A 3-phase 13.2 kV 60 Hz, 50 MVA wye-connected cylindrical rotor synchronous generator has $X_s = 2.49$ ohms/phase and an internally generated voltage at the operating point of 15,767 V_{LL} with a power angle of 11.1 degrees. The machine has 8 poles. Determine:

- the synchronizing power in MW/rad and MW/ mechanical degree
- synchronizing torque in N-n/radian



Lesson 20_et332b.pptx

EXAMPLE 20-2 SOLUTION (1)

Find the per phase quantities of V_T and E_f from the line-to-line values

$$V_{LL} = 13200 \cdot V$$

$$E_{fL} = 15877 \cdot V$$

$$X_s = 2.49 \cdot \text{ohm}$$

$$V_T = \frac{13200 \cdot V}{\sqrt{3}}$$

$$E_f = \frac{15767 \cdot V}{\sqrt{3}}$$

$$\delta = 11.1 \cdot \text{deg}$$

$$V_T = 7621 \cdot V$$

$$E_f = 9103 \cdot V$$

$$P_s = \left[\frac{[3 \cdot (7621 \cdot V)(9103 \cdot V)]}{2.49 \cdot \text{ohm}} \right] \cdot \cos(11.1 \cdot \text{deg}) \quad \text{Watts}$$

Convert to degrees

$$P_s = 82.019 \frac{\text{MW}}{\text{rad}} \quad \text{scaled to MW}$$

$$82.02 \cdot \frac{\pi}{180} = 1.432 \quad \text{MW/elec. degree}$$



Lesson 20_et332b.pptx

EXAMPLE 20-2 SOLUTION (2)

Number of poles is 8, so... $\delta_e = (\delta_m) \cdot (P/2)$

$$P_s = 1.432 \cdot \left(\frac{2}{8 \cdot \text{poles}} \right)$$

$$P_s = 0.358 \text{ MW/Mech. degree}$$

b.) Now compute the synchronizing torque

Compute
synchronous speed

$$n_s = \frac{120 \cdot 60}{8 \cdot \text{poles}} \quad n_s = 900 \text{ RPM}$$

Convert to
Radians/second

$$\omega_s = n_s \cdot \frac{2 \cdot \pi \cdot \text{rad}}{60 \cdot \text{sec}} \quad \omega_s = 94.248 \frac{\text{rad}}{\text{sec}}$$

$$P_s = 358000 \cdot \text{watt} \quad T_s = \frac{P_s}{\omega_s}$$

$$T_s = \frac{358000 \cdot \text{watt}}{94.248 \cdot \left(\frac{\text{rad}}{\text{sec}} \right)} \quad T_s = 3798.5 \frac{\text{N} \cdot \text{m}}{\text{rad}}$$

Lesson 20_et332b.pptx

ET 332b

Ac Motors, Generators and Power Systems

END LESSON 20 ALTERNATOR OPERATION OF SYNCHRONOUS MACHINES