ET 438a Continuous and Digital Control

Homework

Find the final output gain formula of a pressure transducer that has a measurement range of 10 to 100 psi. It has a linear gain of 25 mV/psi. The desired output range is 0-5 Vdc

Fall 2007 hw38a3a.doc